

NY Rising Housing Recovery Program

Applicant: John Doe
Property: 1111 Main Street
Nearby, NY 11111-1111

Home: (111) 111-1111

Assessor: Inspector

Applicant Number: 059-HA-00000-13

Type of Loss: Hurricane

Date Contacted: 9/18/2013

Date of Loss: 10/29/2012

Date Inspected: 9/20/2013

Date Est. Completed: 10/10/2013 3:48 PM

Date Received: 9/18/2013

Date Entered: 10/4/2013

Price List: NYLI7X_SEP13_NASDY
Restoration/Service/Remodel

Estimate: JOHNDOE

NY Rising Housing Recovery Program

JOHNDOE Allowable Activity

Overview

DESCRIPTION	QNTY	UNIT COST	TOTAL
-------------	------	-----------	-------

The Applicant was present at the listed property at the time of inspection. The Applicant is not currently residing in the home. Refer to attached estimate for a detailed description of damages.

PROPERTY DESCRIPTION

The house is a two story, site built, stick framed wood structure with vinyl siding on a slab on grade foundation. The roof covering is asphalt based composition shingles over a felt base sheet with galvanized flashing, fittings and drip edge. The electrical system appears to have been a 200 amp with overhead service. The breaker panel has been replaced. The AC is a window unit which appears to be in undamaged condition. The plumbing system consists of municipal water, waste and gas with underground service to the house. There was no storm debris accumulation on the property.

DAMAGE DESCRIPTION ACCORDING TO THE APPLICANT

The house received approximately three feet of flood water from the storm surge causing damage to the doors, walls, cabinets, floors, electrical and plumbing. Per the Applicant, the roof sustained no damage.

REPAIRS REPORTED TO THE ASSESSOR BY APPLICANT

The entire first floor has been completely torn out up to four feet. Nothing has been replaced or repaired except for the water heater, boiler and electrical breaker panel in the Utility Room.

COMPLETED REPAIRS OBSERVED BY THE ASSESSOR

The boiler, water heater and breaker panel have been replaced. The doors, walls, baseboards, insulation, wood floors, ceramic tile floors and electrical have been removed, but not replaced. See the estimate for details.

Floor 1

Living Room

Height: 8'

Window	3' X 4'	Opens into Exterior
Door	2' 6" X 6' 8"	Opens into UTILITY_ROOM
Door	2' 6" X 6' 8"	Opens into Exterior
Window	3' X 4'	Opens into Exterior

DESCRIPTION	QNTY	UNIT COST	TOTAL
-------------	------	-----------	-------

*****GENERAL ITEMS*****

Final cleaning - construction - Residential	188.61	SF @	0.27 =	50.92
---	--------	------	--------	-------

*****WALLS & CEILINGS*****

Remove Batt insulation - 4" - R13 - paper faced	388.00	SF @	0.36 =	139.68
Remove 1/2" drywall - hung, taped, ready for texture	388.00	SF @	0.64 =	248.32
Remove Baseboard - 3 1/4"	50.67	LF @	0.67 =	33.95
Remove Casing - 2 1/4"	32.00	LF @	0.75 =	24.00
Remove Window sill	6.00	LF @	1.03 =	6.18

*****DOORS & WINDOWS*****

Remove Exterior door - metal - insulated - flush or panel style	1.00	EA @	32.05 =	32.05
---	------	------	---------	-------

*****FLOORING*****

NY Rising Housing Recovery Program

Grand Total Areas:

3,344.43	SF Walls	2,607.07	SF Ceiling	5,951.50	SF Walls and Ceiling
2,607.07	SF Floor	289.67	SY Flooring	464.55	LF Floor Perimeter
0.00	SF Long Wall	0.00	SF Short Wall	439.55	LF Ceil. Perimeter
2,607.07	Floor Area	2,670.84	Total Area	3,344.43	Interior Wall Area
5,972.88	Exterior Wall Area	389.55	Exterior Perimeter of Walls		
4,846.51	Surface Area	48.47	Number of Squares	677.86	Total Perimeter Length
156.81	Total Ridge Length	0.00	Total Hip Length		

NY Rising Housing Recovery Program

Summary for Allowable Activity (AA)

Line Item Total			11,667.80
Permit			1,000.00
Bonding			316.85
General Conditions			760.45
Subtotal			13,745.10
Total Tax(Rep-Maint)	@	8.625%	1,006.36
Replacement Cost Value			\$14,751.46
Net Claim			\$14,751.46

Inspector