

Assessment Check List

Parcel ID#	Damage Address	City	Zip Code
EF-088-AQ	137 Sequams Ln W	West Islip	11795
Provide Site Signage	Yes	No	
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Maintain Landscaping	Yes	No	Current condition
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Normal High Good Bad
Clean Out Debris	Yes	No	Hand
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Yes No Machine
Install Fencing	Yes	No	
	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Board Up Doors/Windows	Yes	No	Front
	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Left Rear Right All
Verify Status of Utilities	Gas	On	Off
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
			Electric
			On Off
			Oil
			Yes No
			<input checked="" type="checkbox"/>
Miscellaneous Site Work	Notes:	No	
Remove Standing Water	Standing Water	Yes	No
Drainage Issues		<input type="checkbox"/>	<input checked="" type="checkbox"/>
	Drainage Issues	Yes	No
		<input type="checkbox"/>	<input checked="" type="checkbox"/>
Pest/Vermin Control	Roaches	Bats	Rats
	NO	NO	NO
			Other: Explain
			NO
Structural Integrity	Good	Bad	Demolish
	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Habitual with Minor Clean up	Yes	No	
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Hazardous/ Environmental Material Abatement	Notes:	NO	
Verify Status of Bulkheads	Yes	No	
	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Provide Security Personnel	Yes	No	
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Notes:	Landscaping is maintained. Bulkhead, dock and deck is in fair condition. No pest control noted. No gas found.		

-
- 1 Front elevation
Date Taken: 7/19/2014
Taken By: Cham Benvenuti



- 2 Street right
Date Taken: 7/19/2014
Taken By: Cham Benvenuti



- 3 Street left
Date Taken: 7/19/2014
Taken By: Cham Benvenutti



- 4 Address and signage
Date Taken: 7/19/2014
Taken By: Cham Benvenutti



5 Front yard
Date Taken: 7/19/2014
Taken By: Cham Benvenuti



6 Left elevation
Date Taken: 7/19/2014
Taken By: Cham Benvenuti



7 Left side yard
Date Taken: 7/19/2014
Taken By: Cham Benvenuti



8 Rear elevation
Date Taken: 7/19/2014
Taken By: Cham Benvenuti



9 Back yard
Date Taken: 7/19/2014
Taken By: Cham Benvenuti



10 Bulkhead and deck
Date Taken: 7/19/2014
Taken By: Cham Benvenuti
Bulkhead in good condition



11 Bulkhead and deck
Date Taken: 7/19/2014
Taken By: Cham Benvenuti
Bulkhead in good condition



12 Rear deck
Date Taken: 7/19/2014
Taken By: Cham Benvenuti



13 Detached structure
Date Taken: 7/19/2014
Taken By: Cham Benvenutti



14 Rear deck
Date Taken: 7/19/2014
Taken By: Cham Benvenutti



15 Right elevation
Date Taken: 7/19/2014
Taken By: Cham Benvenuti



16 Right side yard
Date Taken: 7/19/2014
Taken By: Cham Benvenuti



17 Electricity
Date Taken: 7/19/2014
Taken By: Cham Benvenuti
Connected

