

Parcel ID#	Damage Address	City	Zip Code
EF-097-AQ	3270 Parkway Dr	Baldwin	11510

Provide Site Signage
 Yes No

Maintain Landscaping

Yes	No	Current condition	Normal	High	Good	Bad
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Clean Out Debris

Yes	No	Hand	Yes	No	Machine	Yes	No	Both
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Install Fencing
 Yes No

Board Up Doors/Windows

Yes	No	Front	Left	Rear	Right	All
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Verify Status of Utilities

Gas	On	Off	Electric	On	Off	Oil	Yes	No
<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Miscellaneous Site Work
 Notes:
 Structure appears to be in good overall condition. No access to rear due to fencing. Bulkhead present, unable to determine condition.

Remove Standing Water

Standing Water	Yes	No
<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>

Drainage Issues	Yes	No
<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>

Pest/Vermin Control

Roaches	Bats	Rats	Other: Explain
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A

Structural Integrity

Good	Bad	Demolish
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Habitual with Minor Clean up
 Yes No

Hazardous/ Environmental Material Abatement
 Notes:

Verify Status of Bulkheads
 Yes No

Provide Security Personell
 Yes No

1 Front
Date Taken: 7/22/2014
Taken By: Aujena DuPree



2 Street Left
Date Taken: 7/22/2014
Taken By: Aujena DuPree



-
- 3 Street Right
Date Taken: 7/22/2014
Taken By: Aujena DuPree



- 4 Address
Date Taken: 7/22/2014
Taken By: Aujena DuPree



-
- 5 Signage
Date Taken: 7/22/2014
Taken By: Aujena DuPree



- 6 Front
Date Taken: 7/22/2014
Taken By: Aujena DuPree



7 Front
Date Taken: 7/22/2014
Taken By: Aujena DuPree



8 Front
Date Taken: 7/22/2014
Taken By: Aujena DuPree



9 Front
Date Taken: 7/22/2014
Taken By: Aujena DuPree



10 Front
Date Taken: 7/22/2014
Taken By: Aujena DuPree



11 Right
Date Taken: 7/22/2014
Taken By: Aujena DuPree



12 Garage
Date Taken: 7/22/2014
Taken By: Aujena DuPree



13 Right
Date Taken: 7/22/2014
Taken By: Aujena DuPree



14 Right
Date Taken: 7/22/2014
Taken By: Aujena DuPree



15 Right
Date Taken: 7/22/2014
Taken By: Aujena DuPree



16 Debris on Right
Date Taken: 7/22/2014
Taken By: Aujena DuPree



17 Left
Date Taken: 7/22/2014
Taken By: Aujena DuPree



18 Left
Date Taken: 7/22/2014
Taken By: Aujena DuPree



19 Left
Date Taken: 7/22/2014
Taken By: Aujena DuPree



20 Left
Date Taken: 7/22/2014
Taken By: Aujena DuPree



21 Rear
Date Taken: 7/22/2014
Taken By: Aujena DuPree



22 Rear
Date Taken: 7/22/2014
Taken By: Aujena DuPree



23 Rear
Date Taken: 7/22/2014
Taken By: Aujena DuPree

