

Assessment Check List

| Parcel ID# | Damage Address | City | Zip Code |
|------------|---|---|-------------------------------------|
| FL-052 | 287 Royal Ave. | Riverhead | 11901 |
| | Provide Site Signage | Yes | No |
| | | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| | Maintain Landscaping | Yes | No |
| | | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| | | Current condition | Normal |
| | | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| | | High | Good |
| | | <input type="checkbox"/> | <input type="checkbox"/> |
| | | Bad | <input type="checkbox"/> |
| | Clean Out Debris | Yes | No |
| | | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| | | Hand | Yes |
| | | <input type="checkbox"/> | <input type="checkbox"/> |
| | | No | <input checked="" type="checkbox"/> |
| | | Machine | Yes |
| | | <input type="checkbox"/> | <input type="checkbox"/> |
| | | No | <input checked="" type="checkbox"/> |
| | | Both | <input type="checkbox"/> |
| | Install Fencing | Yes | No |
| | | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| | Board Up Doors/Windows | Yes | No |
| | | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| | | Front | Left |
| | | <input type="checkbox"/> | <input type="checkbox"/> |
| | | Rear | Right |
| | | <input type="checkbox"/> | <input type="checkbox"/> |
| | | All | <input checked="" type="checkbox"/> |
| | Verify Status of Utilities | Gas | On |
| | | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| | | Off | <input type="checkbox"/> |
| | | Electric | On |
| | | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| | | Off | <input type="checkbox"/> |
| | | Oil | Yes |
| | | <input type="checkbox"/> | <input type="checkbox"/> |
| | | No | <input checked="" type="checkbox"/> |
| | Miscellaneous Site Work | Notes: | N/A |
| | | | |
| | Remove Standing Water | Standing Water | Yes |
| | | <input type="checkbox"/> | <input type="checkbox"/> |
| | | No | <input checked="" type="checkbox"/> |
| | Drainage Issues | Drainage Issues | Yes |
| | | <input type="checkbox"/> | <input type="checkbox"/> |
| | | No | <input checked="" type="checkbox"/> |
| | Pest/Vermin Control | Roaches | Bats |
| | | NO | NO |
| | | Rats | Other: Explain |
| | | NO | NO |
| | Structural Integrity | Good | Bad |
| | | <input type="checkbox"/> | <input type="checkbox"/> |
| | | Demolish | <input checked="" type="checkbox"/> |
| | Habitual with Minor Clean up | Yes | No |
| | | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| | Hazardous/ Environmental Material Abatement | Notes: | NO |
| | | | |
| | Verify Status of Bulkheads | Yes | No |
| | | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| | | Good | |
| | Provide Security Personnel | Yes | No |
| | | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| | Notes: | Detached building and bulkheads need repair | |
| | | | |

1 front elevation
Date Taken: 7/21/2014
Taken By: Brook Benvenuti



2 street right
Date Taken: 7/21/2014
Taken By: Brook Benvenuti



3 street left
Date Taken: 7/21/2014
Taken By: Brook Benvenuti



4 address
Date Taken: 7/21/2014
Taken By: Brook Benvenuti



5 front elevation
Date Taken: 7/21/2014
Taken By: Brook Benvenuti



6 front yard
Date Taken: 7/21/2014
Taken By: Brook Benvenuti



7 left yard
Date Taken: 7/21/2014
Taken By: Brook Benvenuti



8 left elevation
Date Taken: 7/21/2014
Taken By: Brook Benvenuti



9 front deck
Date Taken: 7/21/2014
Taken By: Brook Benvenuti



10 rear yard
Date Taken: 7/21/2014
Taken By: Brook Benvenuti



11 rear yard
Date Taken: 7/21/2014
Taken By: Brook Benvenuti



12 rear shed
Date Taken: 7/21/2014
Taken By: Brook Benvenuti



13 rear dock
Date Taken: 7/21/2014
Taken By: Brook Benvenuti



14 rear bulkhead
Date Taken: 7/21/2014
Taken By: Brook Benvenuti



15 rear bulkhead
Date Taken: 7/21/2014
Taken By: Brook Benvenuti



16 rear shed
Date Taken: 7/21/2014
Taken By: Brook Benvenuti



17 rear bulkhead
Date Taken: 7/21/2014
Taken By: Brook Benvenuti



18 gas meter
Date Taken: 7/21/2014
Taken By: Brook Benvenuti



19 power meter
Date Taken: 7/21/2014
Taken By: Brook Benvenuti



20 right yard
Date Taken: 7/21/2014
Taken By: Brook Benvenuti



21 right elevation
Date Taken: 7/21/2014
Taken By: Brook Benvenuti

