

Assessment Check List

Parcel ID#	Damage Address	City	Zip Code
FL-079	26 Pine Ave.	Riverhead	11901
	Provide Site Signage	Yes	No
		<input type="checkbox"/>	<input checked="" type="checkbox"/>
	Maintain Landscaping	Yes	No
		<input checked="" type="checkbox"/>	<input type="checkbox"/>
		Current condition	Normal
		<input type="checkbox"/>	<input checked="" type="checkbox"/>
		High	Good
		<input type="checkbox"/>	<input type="checkbox"/>
		Bad	<input type="checkbox"/>
	Clean Out Debris	Yes	No
		<input checked="" type="checkbox"/>	<input type="checkbox"/>
		Hand	Yes
		<input type="checkbox"/>	<input checked="" type="checkbox"/>
		No	<input type="checkbox"/>
		Machine	Yes
		<input type="checkbox"/>	<input type="checkbox"/>
		No	<input checked="" type="checkbox"/>
		Both	<input type="checkbox"/>
	Install Fencing	Yes	No
		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	Board Up Doors/Windows	Yes	No
		<input type="checkbox"/>	<input checked="" type="checkbox"/>
		Front	Left
		<input type="checkbox"/>	<input type="checkbox"/>
		Rear	Right
		<input type="checkbox"/>	<input type="checkbox"/>
		All	<input type="checkbox"/>
	Verify Status of Utilities	Gas	On
		<input type="checkbox"/>	<input type="checkbox"/>
		Off	<input checked="" type="checkbox"/>
		Electric	On
		<input type="checkbox"/>	<input type="checkbox"/>
		Off	<input checked="" type="checkbox"/>
		Oil	Yes
		<input type="checkbox"/>	<input type="checkbox"/>
		No	<input checked="" type="checkbox"/>
	Miscellaneous Site Work	Notes:	N/A
	Remove Standing Water	Standing Water	Yes
		<input type="checkbox"/>	<input type="checkbox"/>
		No	<input checked="" type="checkbox"/>
	Drainage Issues	Drainage Issues	Yes
		<input type="checkbox"/>	<input type="checkbox"/>
		No	<input checked="" type="checkbox"/>
	Pest/Vermin Control	Roaches	Bats
		NO	NO
		Rats	Other: Explain
		NO	NO
	Structural Integrity	Good	Bad
		<input type="checkbox"/>	<input type="checkbox"/>
		Demolish	<input checked="" type="checkbox"/>
	Habitual with Minor Clean up	Yes	No
		<input type="checkbox"/>	<input checked="" type="checkbox"/>
	Hazardous/ Environmental Material Abatement	Notes:	NO
	Verify Status of Bulkheads	Yes	No
		<input type="checkbox"/>	<input type="checkbox"/>
		N/A	
	Provide Security Personnel	Yes	No
		<input type="checkbox"/>	<input checked="" type="checkbox"/>
	Notes:	Structure foundation damaged. No pest control on-site	

1 front elevation
Date Taken: 7/21/2014
Taken By: Brook Benvenuti



2 street right
Date Taken: 7/21/2014
Taken By: Brook Benvenuti



3 street left
Date Taken: 7/21/2014
Taken By: Brook Benvenuti



4 front yard
Date Taken: 7/21/2014
Taken By: Brook Benvenuti



5 front yard
Date Taken: 7/21/2014
Taken By: Brook Benvenuti



6 front elevation
Date Taken: 7/21/2014
Taken By: Brook Benvenuti



7 power off
Date Taken: 7/21/2014
Taken By: Brook Benvenuti



8 foundation damage
Date Taken: 7/21/2014
Taken By: Brook Benvenuti



9 gas off
Date Taken: 7/21/2014
Taken By: Brook Benvenuti



10 foundation damage
Date Taken: 7/21/2014
Taken By: Brook Benvenuti



11 left elevation
Date Taken: 7/21/2014
Taken By: Brook Benvenuti



12 left elevation
Date Taken: 7/21/2014
Taken By: Brook Benvenuti



13 left side
Date Taken: 7/21/2014
Taken By: Brook Benvenuti



14 left yard
Date Taken: 7/21/2014
Taken By: Brook Benvenuti



15 rear debris
Date Taken: 7/21/2014
Taken By: Brook Benvenuti



16 rear debris
Date Taken: 7/21/2014
Taken By: Brook Benvenuti



17 rear elevation
Date Taken: 7/21/2014
Taken By: Brook Benvenuti



18 rear damage
Date Taken: 7/21/2014
Taken By: Brook Benvenuti



19 right yard
Date Taken: 7/21/2014
Taken By: Brook Benvenuti



20 rear right
Date Taken: 7/21/2014
Taken By: Brook Benvenuti



21 right debris
Date Taken: 7/21/2014
Taken By: Brook Benvenuti



22 foundation damage
Date Taken: 7/21/2014
Taken By: Brook Benvenuti

