

Parcel ID#	Damage Address	City	Zip Code
LH-051	885 S Bay St	Lindenhurst	11757

Provide Site Signage Yes No

Maintain Landscaping

Yes	No	Current condition	Normal	High	Good	Bad
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>

Clean Out Debris

Yes	No	Hand	Yes	No	Machine	Yes	No	Both
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Install Fencing Yes No

Board Up Doors/Windows

Yes	No	Front	Left	Rear	Right	All
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>

Verify Status of Utilities

Gas	On	Off	Electric	On	Off	Oil	Yes	No
<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Miscellaneous Site Work

Notes:
Structure appears to be in overall good condition. Rear landscaping needs attention

Remove Standing Water

Standing Water	Yes	No
<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>

Drainage Issues	Yes	No
<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>

Pest/Vermin Control

Roaches	Bats	Rats	Other: Explain
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A

Structural Integrity

Good	Bad	Demolish
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Habitual with Minor Clean up Yes No

Hazardous/ Environmental Material Abatement

Notes:

Verify Status of Bulkheads Yes No

Provide Security Personell Yes No

1 Front
Date Taken: 7/14/2014
Taken By: Aujena DuPree



2 Front
Date Taken: 7/14/2014
Taken By: Aujena DuPree



3 Front
Date Taken: 7/14/2014
Taken By: Aujena DuPree



4 Street Left
Date Taken: 7/14/2014
Taken By: Aujena DuPree



-
- 5 Street Right
Date Taken: 7/14/2014
Taken By: Aujena DuPree



- 6 Breezeway
Date Taken: 7/14/2014
Taken By: Aujena DuPree



7 Breezeway
Date Taken: 7/14/2014
Taken By: Aujena DuPree



8 Breezeway
Date Taken: 7/14/2014
Taken By: Aujena DuPree



9 Address
Date Taken: 7/14/2014
Taken By: Aujena DuPree



10 Front Door
Date Taken: 7/14/2014
Taken By: Aujena DuPree



11 Front
Date Taken: 7/14/2014
Taken By: Aujena DuPree



12 Front Yard
Date Taken: 7/14/2014
Taken By: Aujena DuPree



13 Left Elevation
Date Taken: 7/14/2014
Taken By: Aujena DuPree



14 Left Elevation
Date Taken: 7/14/2014
Taken By: Aujena DuPree



15 Left Elevation
Date Taken: 7/14/2014
Taken By: Aujena DuPree



16 Rear Elevation
Date Taken: 7/14/2014
Taken By: Aujena DuPree



17 Rear Elevation
Date Taken: 7/14/2014
Taken By: Aujena DuPree



18 Backyard
Date Taken: 7/14/2014
Taken By: Aujena DuPree



19 Backyard
Date Taken: 7/14/2014
Taken By: Aujena DuPree



20 Shed
Date Taken: 7/14/2014
Taken By: Aujena DuPree



21 Fenced Cage

Date Taken: 7/14/2014

Taken By: Aujena DuPree

Located in backyard at right elevation entrance



22 Crawlspace

Date Taken: 7/14/2014

Taken By: Aujena DuPree



23 Right Elevation
Date Taken: 7/14/2014
Taken By: Aujena DuPree

