Parcel ID#	Damage Address	City	Zip Code
OAK-006	438 Shore Dr	Oakdale	11769

	Yes	
Provide Site Signage		X

	Yes	No	Current condition	Normal	High	Good	Bad
Maintain Landscaping	X				X		X

	Yes	No	Hand	Yes	No	Machine	Yes	No	Both
Clean Out Debris	X			X				X	

	Yes	No
Install Fencing	X	

	Yes	No	Front	Left	Rear	Right	All
Board Up Doors/Windows	X						X

	Gas	On	Off	Electric	On	Off	Oil	Yes	No
Verify Status of Utilities			X		X				

Miscellaneous Site Work

Notes:

	Standing Water	Yes	No
Remove Standing Water			X

	Drainage Issues	Yes	No
Drainage Issues			X

	Roaches	Bats	Rats	Other: Explain
Pest/Vermin Control				N/A

	Good	Bad	Demolish
Structural Integrity	X		

	Yes	No
Habitual with Minor Clean up	X	

Hazadorous/ Enviornmental Material Abatement

Notes:

	Yes	No
Verify Status of Bulkheads	X	

	Yes	No
Provide Security Personell		X

1 Front
Date Taken: 7/14/2014
Taken By: Aujena DuPree

2 Front
Date Taken: 7/14/2014
Taken By: Aujena DuPree

3 Right Elevation
Date Taken: 7/14/2014
Taken By: Aujena DuPree

4 Street Left
Date Taken: 7/14/2014
Taken By: Aujena DuPree

5 Street Right
Date Taken: 7/14/2014
Taken By: Aujena DuPree

6 Front
Date Taken: 7/14/2014
Taken By: Aujena DuPree

7 Front
Date Taken: 7/14/2014
Taken By: Aujena DuPree

8 Front Garage
Date Taken: 7/14/2014
Taken By: Aujena DuPree

9 Front Yard
Date Taken: 7/14/2014
Taken By: Aujena DuPree

10 Front Yard
Date Taken: 7/14/2014
Taken By: Aujena DuPree

11 Left Elevation
Date Taken: 7/14/2014
Taken By: Aujena DuPree

12 Left Elevation
Date Taken: 7/14/2014
Taken By: Aujena DuPree

13 Shed 1
Date Taken: 7/14/2014
Taken By: Aujena DuPree

14 Rear of Property
Date Taken: 7/14/2014
Taken By: Aujena DuPree

15 Rear Fencing
Date Taken: 7/14/2014
Taken By: Aujena DuPree

16 Rear Elevation
Date Taken: 7/14/2014
Taken By: Aujena DuPree

17 Oil Tank
Date Taken: 7/14/2014
Taken By: Aujena DuPree

Oil Tank in rear elevation

18 Rear Elevation
Date Taken: 7/14/2014
Taken By: Aujena DuPree

19 Basement Window
Date Taken: 7/14/2014
Taken By: Aujena DuPree

20 Shed 2
Date Taken: 7/14/2014
Taken By: Aujena DuPree

21 Right Elevation
Date Taken: 7/14/2014
Taken By: Aujena DuPree

22 Rear Elevation
Date Taken: 7/14/2014
Taken By: Aujena DuPree

23 Rear Elevation
Date Taken: 7/14/2014
Taken By: Aujena DuPree

24 Rear Elevation
Date Taken: 7/14/2014
Taken By: Aujena DuPree

25 Rear Elevation
Date Taken: 7/14/2014
Taken By: Aujena DuPree

26 Debris
Date Taken: 7/14/2014
Taken By: Aujena DuPree

Debris on right elevation

27 Right Elevation
Date Taken: 7/14/2014
Taken By: Aujena DuPree

28 Right Elevation
Date Taken: 7/14/2014
Taken By: Aujena DuPree