

Parcel ID#	Damage Address	City	Zip Code
OAK-013	567 Shore Dr	Oakdale	11769

Provide Site Signage  Yes  No

Maintain Landscaping  Yes  No  Current condition  Normal  High  Good  Bad

Clean Out Debris  Yes  No  Hand  Yes  No  Machine  Yes  No  Both

Install Fencing  Yes  No

Board Up Doors/Windows  Yes  No  Front  Left  Rear  Right  All

Verify Status of Utilities  Gas  On  Off  Electric  On  Off  Oil  Yes  No

Miscellaneous Site Work  
 Notes:  
 Oil tank present, needs to be removed. Second story unfinished addition. Property is hazardous and should be given immediate attention.

Remove Standing Water  Standing Water  Yes  No

Drainage Issues  Yes  No

Pest/Vermin Control  Roaches  Bats  Rats  Other: Explain N/A

Structural Integrity  Good  Bad  Demolish

Habitual with Minor Clean up  Yes  No

Hazardous/ Environmental Material Abatement  
 Notes:

Verify Status of Bulkheads  Yes  No N/A

Provide Security Personell  Yes  No

---

1 Front  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree



2 Front  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree



- 
- 3 Right Elevation  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree



- 4 Street Left  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree



- 
- 5 Street Right  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree



- 6 Front  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree



7 Front  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree



8 Front Garage  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree



---

9 Front Yard  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree



10 Front Yard  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree



---

11 Left Elevation  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree



12 Left Elevation  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree



---

13 Shed 1  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree



14 Rear of Property  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree





---

15 Rear Fencing  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree



16 Rear Elevation  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree



---

17 Oil Tank  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree  
Oil Tank in rear elevation



18 Rear Elevation  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree



---

19 Basement Window  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree



20 Shed 2  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree



---

21 Right Elevation  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree



22 Rear Elevation  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree



---

23 Rear Elevation  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree



24 Rear Elevation  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree



---

25 Rear Elevation  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree



26 Debris  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree  
Debris on right elevation



---

27 Right Elevation  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree



28 Right Elevation  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree

