

# Assessment Check List

Parcel ID#	Damage Address	City	Zip Code																		
OBBO-046	91 Tarlton St.	Staten Island	10306																		
Provide Site Signage	<table border="1"> <tr> <td>Yes</td> <td>No</td> </tr> <tr> <td>X</td> <td></td> </tr> </table>			Yes	No	X															
Yes	No																				
X																					
Maintain Landscaping	<table border="1"> <tr> <td>Yes</td> <td>No</td> <td>Current condition</td> <td>Normal</td> <td>High</td> <td>Good</td> <td>Bad</td> </tr> <tr> <td>X</td> <td></td> <td></td> <td></td> <td>X</td> <td></td> <td></td> </tr> </table>			Yes	No	Current condition	Normal	High	Good	Bad	X				X						
Yes	No	Current condition	Normal	High	Good	Bad															
X				X																	
Clean Out Debris	<table border="1"> <tr> <td>Yes</td> <td>No</td> <td>Hand</td> <td>Yes</td> <td>No</td> <td>Machine</td> <td>Yes</td> <td>No</td> <td>Both</td> </tr> <tr> <td>X</td> <td></td> <td></td> <td>X</td> <td></td> <td></td> <td>X</td> <td></td> <td></td> </tr> </table>			Yes	No	Hand	Yes	No	Machine	Yes	No	Both	X			X			X		
Yes	No	Hand	Yes	No	Machine	Yes	No	Both													
X			X			X															
Install Fencing	<table border="1"> <tr> <td>Yes</td> <td>No</td> </tr> <tr> <td></td> <td>X</td> </tr> </table>			Yes	No		X														
Yes	No																				
	X																				
Board Up Doors/Windows	<table border="1"> <tr> <td>Yes</td> <td>No</td> <td>Front</td> <td>Left</td> <td>Rear</td> <td>Right</td> <td>All</td> </tr> <tr> <td></td> <td>X</td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </table>			Yes	No	Front	Left	Rear	Right	All		X									
Yes	No	Front	Left	Rear	Right	All															
	X																				
Verify Status of Utilities	<table border="1"> <tr> <td>Gas</td> <td>On</td> <td>Off</td> <td>Electric</td> <td>On</td> <td>Off</td> <td>Oil</td> <td>Yes</td> <td>No</td> </tr> <tr> <td></td> <td></td> <td>X</td> <td></td> <td></td> <td>X</td> <td></td> <td></td> <td>X</td> </tr> </table>			Gas	On	Off	Electric	On	Off	Oil	Yes	No			X			X			X
Gas	On	Off	Electric	On	Off	Oil	Yes	No													
		X			X			X													
Miscellaneous Site Work	<table border="1"> <tr> <td>Notes:</td> <td colspan="3">N/A</td> </tr> </table>			Notes:	N/A																
Notes:	N/A																				
Remove Standing Water	<table border="1"> <tr> <td>Standing Water</td> <td>Yes</td> <td>No</td> </tr> <tr> <td></td> <td></td> <td>X</td> </tr> </table>			Standing Water	Yes	No			X												
Standing Water	Yes	No																			
		X																			
Drainage Issues	<table border="1"> <tr> <td>Drainage Issues</td> <td>Yes</td> <td>No</td> </tr> <tr> <td></td> <td></td> <td>X</td> </tr> </table>			Drainage Issues	Yes	No			X												
Drainage Issues	Yes	No																			
		X																			
Pest/Vermin Control	<table border="1"> <tr> <td>Roaches</td> <td>Bats</td> <td>Rats</td> <td>Other: Explain</td> </tr> <tr> <td>NO</td> <td>NO</td> <td>NO</td> <td>NO</td> </tr> </table>			Roaches	Bats	Rats	Other: Explain	NO	NO	NO	NO										
Roaches	Bats	Rats	Other: Explain																		
NO	NO	NO	NO																		
Structural Integrity	<table border="1"> <tr> <td>Good</td> <td>Bad</td> <td>Demolish</td> </tr> <tr> <td></td> <td></td> <td>X</td> </tr> </table>			Good	Bad	Demolish			X												
Good	Bad	Demolish																			
		X																			
Habitual with Minor Clean up	<table border="1"> <tr> <td>Yes</td> <td>No</td> </tr> <tr> <td></td> <td>X</td> </tr> </table>			Yes	No		X														
Yes	No																				
	X																				
Hazardous/ Environmental Material Abatement	<table border="1"> <tr> <td>Notes:</td> <td colspan="3">NO</td> </tr> </table>			Notes:	NO																
Notes:	NO																				
Verify Status of Bulkheads	<table border="1"> <tr> <td>Yes</td> <td>No</td> </tr> <tr> <td></td> <td></td> </tr> </table> N/A			Yes	No																
Yes	No																				
Provide Security Personnel	<table border="1"> <tr> <td>Yes</td> <td>No</td> </tr> <tr> <td></td> <td>X</td> </tr> </table>			Yes	No		X														
Yes	No																				
	X																				
Notes:	Structure is scheduled for demolition. Heavy debris on site.																				

1 Front  
Date Taken: 7/15/2014  
Taken By: Brook Benvenuti



2 Street right  
Date Taken: 7/15/2014  
Taken By: Brook Benvenuti



---

3 Street left  
Date Taken: 7/15/2014  
Taken By: Brook Benvenuti



4 Address  
Date Taken: 7/15/2014  
Taken By: Brook Benvenuti



5 Front  
Date Taken: 7/15/2014  
Taken By: Brook Benvenuti



6 Front  
Date Taken: 7/15/2014  
Taken By: Brook Benvenuti



7 Rear  
Date Taken: 7/15/2014  
Taken By: Brook Benvenuti



8 Rear  
Date Taken: 7/15/2014  
Taken By: Brook Benvenuti




9 Sign  
Date Taken: 7/15/2014  
Taken By: Brook Benvenuti



10 Sign  
Date Taken: 7/15/2014  
Taken By: Brook Benvenuti



11 Sign  
Date Taken: 7/15/2014  
Taken By: Brook Benvenuti



12 Sign  
Date Taken: 7/15/2014  
Taken By: Brook Benvenuti



13 Side  
Date Taken: 7/15/2014  
Taken By: Brook Benvenuti



14 Side  
Date Taken: 7/15/2014  
Taken By: Brook Benvenuti





---

15 Side  
Date Taken: 7/15/2014  
Taken By: Brook Benvenuti



16 Rear  
Date Taken: 7/15/2014  
Taken By: Brook Benvenuti



---

17 Utilities  
Date Taken: 7/15/2014  
Taken By: Brook Benvenuti



18 Debris  
Date Taken: 7/15/2014  
Taken By: Brook Benvenuti



---

19 Debris  
Date Taken: 7/15/2014  
Taken By: Brook Benvenuti



20 Debris  
Date Taken: 7/15/2014  
Taken By: Brook Benvenuti

