

Parcel ID#	Damage Address	City	Zip Code
VP-035	14 Dewitt Ave	Patchogue	11772

Provide Site Signage  Yes  No

Maintain Landscaping  Yes  No  Current condition  Normal  High  Good  Bad

Clean Out Debris  Yes  No  Hand  Yes  No  Machine  Yes  No  Both

Install Fencing  Yes  No

Board Up Doors/Windows  Yes  No  Front  Left  Rear  Right  All

Verify Status of Utilities  Gas  On  Off  Electric  On  Off  Oil  Yes  No

Miscellaneous Site Work  
 Notes:  
 Property is hazardous and should be demolished immediately. All doors and windows are missing, none boarded up.

Remove Standing Water  Standing Water  Yes  No  
 Drainage Issues  Yes  No

Pest/Vermin Control  Roaches  Bats  Rats  Other: Explain N/A

Structural Integrity  Good  Bad  Demolish

Habitual with Minor Clean up  Yes  No

Hazardous/ Environmental Material Abatement  
 Notes:

Verify Status of Bulkheads  Yes  No N/A

Provide Security Personell  Yes  No

- 
- 1 Front  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree



- 2 Address  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree



---

3 Street Left  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree



4 Street Right  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree



---

5 Street in Front  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree



6 Debris  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree  
Debris in front yard



- 
- 7 Garage  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree



- 8 Front Interior  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree



- 
- 9 Front Porch  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree



- 10 Posted on Fence  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree



---

11 Right Elevation  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree



12 Right Elevation  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree  
All windows missing



---

13 Right Elevation  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree



14 Right Fencing  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree





---

15 Rear Elevation  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree



16 Rear Elevation  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree



---

17 Interior  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree



18 Interior  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree



---

19 Interior  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree



20 Rear Staircase  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree



---

21 Left Elevation  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree



22 Rear of Garage  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree



---

23 Deck  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree



24 Roof  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree  
Railing of roof is missing



---

25 Roof Railing  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree



26 Deck  
Date Taken: 7/14/2014  
Taken By: Aujena DuPree  
Hole in deck

